


DONNING (PUTTING ON) PERSONAL PROTECTIVE EQUIPMENT (PPE)

DROPLET & CONTACT AND AIRBORNE PRECAUTIONS WITH AGMPs (AEROSOL-GENERATING MEDICAL PROCEDURES)

PREPARE

- Engage with peer support to ensure PPE is put on correctly using the checklist
- Ensure you have all the PPE equipment you will need before proceeding
- Remove all personal items and empty pockets leave outside the room (i.e. lanyards, jewelry, cell phones, etc.)
- Ensure hair is properly tied back
- Inspect PPE for any defects (i.e. holes in gown or gloves, knots or missing ties, goggles/face shield intact, etc.) and
- Replace any PPE if defects are found

1 PERFORM HAND HYGIENE



- Perform hand hygiene for 20 seconds, cleaning all surfaces of hands and wrists
- Use alcohol based handrub (ABHR) or soap and water.
- If hands are soiled, use soap and water.

2 DON/PUT ON GOWN



- Put on gown and wrap around the back
- Ensure that the gown covers the torso of body from the neck to knees to wrist
- Fasten the gown securely at both the back of the neck and the waist

FOR PATIENTS ON DROPLET & CONTACT PRECAUTIONS WITHOUT AGMP

3A DON/PUT ON SURGICAL/PROCEDURE MASK



- Secure the ties or elastic around your head so mask stays in place
- Fit the mouldable band to the bridge of nose to prevent manipulating it during care
- Ensure nose, mouth and chin are covered with minimal gap between mask and face

FOR PATIENTS ON AIRBORNE PRECAUTIONS OR WITH AGMP

3B DON/PUT ON N95 MASK



- Pre-stretch both top and bottom straps before placing the N95 mask on your face
- Cup the N95 mask in your hand and position it under your chin with the nose piece up
- Secure the elastic band around your head so the N95 mask stays in place
- Use both hands to mold the metal of the N95 mask around the bridge of your nose
- Perform a proper seal check above the nose and below the chin

4 DON/PUT ON EYE PROTECTION (GOGGLES OR FACE SHIELD, IF NOT CONNECTED TO MASK ABOVE)



- Place goggles or face shield over face and eyes
- Adjust to fit and ensure minimal movement
- If wearing personal glasses, goggles or a full face shield must be worn overtop

5 DON/PUT ON GLOVES



- Put on a pair of gloves ensuring no gap between glove and gown
- Pull sleeves of gown down to facilitate proper glove placement
- Extend gloves to cover wrist of gown

FINAL CHECK



- Perform double check with peer support to ensure PPE is on correctly